Serial No.: 10/608,012

IN THE SPECIFICATION

Please amend the paragraph on page 4, line 16 as follows:

The power engine structure 5 has a longitudinal axis X'X crossed by a radial plan plane YOZ and the support 7 is oriented in such a way that the dynamic absorbers 15a, 15b, are induced to move in the radial plan plane YOZ of the power engine structure 5.